

# Welltech Product Release Note

Date:2009/06/29

<b>Division:</b>	<b>SDD1</b>	<b>Releaser:</b>	<b>Songyo</b>
<b>Model Name:</b>	<b>WellGate26xx product line</b>	<b>Object:</b>	<input type="checkbox"/> H.W. <input checked="" type="checkbox"/> S.W.
<b>Subject:</b>	<b>release firmware : wg26xx_ap_106c</b>		
<b>Release contents</b>			
<b>Bug Fixed</b>			
<p>1. Network fail to start when the leading 0 is not stripped (e.g. 192.168.018.018)</p> <p>2. Fixed the DSP download failure occasionally during boot up.</p>			
<b>Feature and Function Added</b>			
<p>1. Added a timer to delay answer the VOIP incoming call to FXO when PSTN line doesn't support polarity reverse.</p> <p>2. When PABX mode is enabled and the FXS line is also registered, FXS do the routing based on the FXO prefix routing table. (2644 only)</p> <p>3. Increased voice volume for FXS and FXO. It is recommended to change the voice volume as follows at default setting.</p> <p style="padding-left: 20px;">FXO: remove receive volume -3 db, local receive volume: 0 db</p> <p style="padding-left: 20px;">FXS: remove receive volume 0 db, local receive volume: - 3 or -6 db</p>			
<b>Configuration Item Changed</b>			
<b>Application Block Diagram</b>			
<b>Hyperlink</b>			
<p>WELLTECH WEB Site:<a href="http://www.welltech.com">http://www.welltech.com</a></p> <p>Firmware Download: <a href="http://www.welltech.com/support/26xx.htm">http://www.welltech.com/support/26xx.htm</a></p> <p>User Manual: <a href="http://www.welltech.com/support/26xx.htm">http://www.welltech.com/support/26xx.htm</a></p>			
<b>Note</b>			