

Model Name:	3701/3702	Object:	<input type="checkbox"/> H.W.	<input checked="" type="checkbox"/> S.W.
Subject:	Release SIP firmware of 3701/3702: sipfxso.106			
Release content				
Bug fixed				
1.	Follow the theory of the manufacturer to fix the source code for CPU, otherwise the 370x may not boot successfully with new hardware.			
2.	Fix the bug of AutoDNS. The DNS does not follow the DHCP even you enable the "autodns" function.			
Feature and Function added				
None				
Configuration item changed				
1.	Change the default keypad type to RFC2833			
2.	Change the default payload type to 101 (RFC2833) and 96 (FAX)			
3.	Remove some configure item from the Web interface, including tone setting, FXO password and commit. Because the Flash ROM is not enough.			
4.	The configuration will be "commit" if user inputs the new setting and press OK via the Web manage interface. (But user still need to input commit if the new setting are set via CLI)			
Note				
None				