

Release Note

Model Name:	3502/3502a/3504a	object	<input type="radio"/> H.W. <input checked="" type="radio"/> S.W.
Subject:	Release SIP version firmware of 3502/02a/04a:2sipfxs.114/2asipfxs.114/4asipfxs.114		
Release content			
Bug fixed			
<p>1. Modified 180 include SDP issue. When the 180 include SDP it will have one way voice problem, because CPE receive the 180 include SDP will open voice channel then receive 200 ok will close and open channel again, therefore CPE occur one way voice, in this firmware this bug has fixed.</p> <p>2. When the Asterisk continue to send Notify message to our device, our 35 device will stop sending register message.</p>			
Feature and Function added			
<p>1. Added security encrypt RC4 format Ifaddr –security 2 (0:off 1:MD5 2:RC4)</p> <p>2. Added caller id BT format, this type is used in the Britain Sysconf –callerid 0 (0:disable 1:fsk(bellcore) 2:DTMF 3:fsk(ETSI) 4:BT)</p> <p>Above both functions is added and displayed in the web page.</p>			
Configuration item changed			
Note			