

# Welltech Product Release Note

Date:2009/05/11

<b>Division:</b>	SDD1	<b>Releaser:</b>	songyo
<b>Model Name:</b>	WillGate26xx	<b>Object:</b>	<input type="checkbox"/> H.W. <input checked="" type="checkbox"/> S.W.
<b>Subject:</b>	release firmware : wg26xx v105b		
<b>Release contents</b>			
<b>Bug Fixed</b>			
<p>1. Failed to make P2P call when there is no any line was configured to register.</p> <p>2. Occasionally, the Wellgate 2680 or 2644 will not process the call (either answer or routing) due to the wrong ring count calculation algorithm.</p>			
<b>Feature and Function Added</b>			
<b>Configuration Item Changed</b>			
<b>Application Block Diagram</b>			
<b>Hyperlink</b>			
WELLTECH WEB Site: <a href="http://www.welltech.com">http://www.welltech.com</a> Firmware Download: <a href="http://www.welltech.com/support/26xx_cht.htm">http://www.welltech.com/support/26xx_cht.htm</a> User Manual: <a href="http://www.welltech.com/support/26xx_cht.htm">http://www.welltech.com/support/26xx_cht.htm</a>			
<b>Note</b>			