

Welltech Product Release Note

Date:04/22/2010

Division:	SDD1	Releaser:	Songyo
Model Name:	WellGate2608, 2680 and 2644	Object:	<input type="checkbox"/> H.W. <input checked="" type="checkbox"/> S.W.
Subject:	release firmware : wg26xx_ap_107a		
Release contents			
Bug Fixed			
<ol style="list-style-type: none">1. After upgrade, SIP proxy IP address will be reset to default which is 10.1.1.2. This patch will keep the original setting.2. In 2644 PABX mode, if FXS is off hook and at that time reboot. The corresponding FXO will be off hook after reboot. However, the LED is still in idle state.3. P2P call cannot work correctly. It was fixed.4. For a VOIP incoming and hunting to a FXO port, if the dialed number contains "p" which is a pause, it will ignore the dialed number after p. It was fixed.5. When 26xx is in calling state and receive a Fax answer tone from VOIP, it will send reinvite to the called party asking for T.38 transmission. Now by default, it will ignore the answer tone when 26xx is in calling state.			
Feature and Function Added			
WEB Configuration Item Changed			
Application Block Diagram			
Hyperlink			
WELLTECH WEB Site: http://www.welltech.com Firmware Download: http://www.welltech.com/support/26xx.htm User Manual: http://www.welltech.com/support/26xx.htm			
Note			