

Welltech Product Release Note

Date:2009/06/08

Division:	SDD1	Releaser:	Songyo
Model Name:	WillGate26xx product Line	Object:	<input type="checkbox"/> H.W. <input checked="" type="checkbox"/> S.W.
Subject:	release firmware : wg26xx v106b		
Release contents			
Bug Fixed			
<p>1. The voice delay happened on Wellgate 2644 when all 4 FXO ports are routed to FXS port and talking simultaneously.</p> <p>2. Filter the very short ring indicator for FXO port to avoid the fake ring signal event.</p> <p>3. For 2644, when the FXO incoming call is routed to VOIP and FXS is using FXO for outgoing fax, the FXS cannot do fax any more after FXO had a success T.38 transmission.</p>			
Feature and Function Added			
Configuration Item Changed			
Application Block Diagram			
Hyperlink			
WELLTECH WEB Site: http://www.welltech.com			
Firmware Download: http://www.welltech.com/support/26xx_cht.htm			
User Manual: http://www.welltech.com/support/26xx_cht.htm			
Note			