

Release Note

Date / Time: 94/06/29

Model Name:	LP201 SIP Version
Subject:	Lp201sip.103
Release content	
Bug fixed	
1.The RTCP function issue, send RTCP every 5 seconds. 2.[*]function speed dial problem.	
Feature and Function added	
1.Command line prefix priority: prefix(drop/insert)--->pbook(enable)--->prefix string 2.Prefix web command	
Configuration item changed	
Note	