

Release Note

Division:	產品開發處	Releaser:	Jason
Model Name:	Lp201	Object:	<input type="checkbox"/> H.W. <input checked="" type="checkbox"/> S.W.
Subject:	Release lp201 new sip app code :lp201sip.104		
Release content			
Bug fixed			
<ol style="list-style-type: none">1. Fixed when using LCD interface to upgrade new firmware that can't download successfully.2. Fixed DHCP issue when LP201 can't get IP behind some special IP-sharing device.3. In version 103, the sip listen port is disappeared when LP201 is under P2P mode. This version solves this problem.			
Feature and Function added			
<ol style="list-style-type: none">1. Added secondary px function: When you want to using the function, you must set it such as primary px on TELNET command line or WEB interface. Command: sip -px2 x.x.x.x			
Configuration item changed			
Delete session Expire function.			
Note			
<ol style="list-style-type: none">1. Secondary px function: LCD doesn't this function command. Only TELNET command line and WEB have support.			