



Model Name:	Lp305	Object:	 H.W.	 S.W.
Subject:	Release SIP firmware of LP305: LP305sip.102			
Release content				
Bug Fixed				
<ol style="list-style-type: none"> 1. Fixed user can't adjust volume when answer call by headset. 2. Fixed when sets wrong default gateway IP, the system of LP305 will crash. Under sets Fixed IP mode and sets wrong default Gateway IP, the system will crash and it will reboot system again and again. User just resets Network configuration from Boot mode. 				
Feature and Function added				
Configuration item changed				
Note				
<ol style="list-style-type: none"> 1. Incomplete Feature <ol style="list-style-type: none"> 1.1 VLAN function. 1.2 Pbook's "insert" and "drop prefix" function. 1.3 Session timer. 1.4 DDNS function. 1.5 Prefix function. 				