

Date / Time: 2006/09/11

Division:	產品開發處	Releaser:	Jason
Model Name:	Lp388	Object:	<input type="checkbox"/> H.W. <input checked="" type="checkbox"/> S.W.
Subject:	Release lp388 new sip app code :lp388sip.100		
Release content			
Alive Bug			
<ol style="list-style-type: none">1. Under Conference state, LP388 can't adjust voice volume.2. Codec G723 High rate problem: When using this Codec It produces noise easily.3. User can't hear ring tone from Headset.			
Incomplete Feature			
<ol style="list-style-type: none">1. Provision server2. Blind transfer Function Key.			
Feature item			
<ol style="list-style-type: none">1. Headset2. Display name.3. DHCP re-searching.4. STUN function. You must enable "ipsharing" function first then you can enable STUN function and input STUN address. (ifaddr -ipsharing 1; ifaddr -stun 1 218.32.223.1)5. Added Function Keys configuration from WEB management page: Advanced→ System Configuration→ " Function Key Configuration."			