

Welltech Product Release Note

Date:2010/02/05

Division:	SDD1	Releaser:	Songyo
Model Name:	LP399	Object:	<input type="checkbox"/> H.W. <input checked="" type="checkbox"/> S.W.
Subject:	release firmware LP-399_110.rom		
Release contents			
Bug Fixed			
1. Fixed PPTP and L2TP started can't access to WEB for WAN port. 2. When VLAN enable, it will disconnect or cause system crash in conversation that network set as bridge mode and pc connect to LAN port.			
Feature and Function Added			
Configuration Item Changed			
Application Block Diagram			
Hyperlink			
WELLTECH WEB Site: http://www.welltech.com Firmware Downloadh: http://www.welltech.com/support/lanphone_399.htm User Manual:			
Note			
1.login user root's password changed to "test" 2. if your firmware is version 108 before, please add the "speakerset,htm" on the web address after. Example: if the LP-399 IP is 10.1.1.3, please input 10.1.1.3:9999/speakerset.htm. You will see speaker phone setting and can choose Half-Duples and Full-Duples			