

| | | | |
|--|---|----------------|--|
| Model Name: | 3802A/3804A | Object: | <input type="checkbox"/> H.W. <input checked="" type="checkbox"/> S.W. |
| Subject: | Release SIP firmware of 3802A/3804A: 2Asipfxo.100e/ 4Asipfxo.100e | | |
| Release content | | | |
| Bug fixed | | | |
| <p>Sometimes the FXO gateway can not answer the PSTN incoming call.</p> <p>This problem is due to some kinds of traditional PBXs will generate some special signal and the FXO gateway will Detect "LOOP" event then close channel. We fix this bug and make the 3802A/3804A more stable with most of PBXs.</p> | | | |
| Feature and Function added | | | |
| None | | | |
| Configuration item changed | | | |
| Set the "ring before answer" time back to 1 (the ring before answer time is 3 within version 4Asipfxo.100d) | | | |
| Note | | | |
| None | | | |