

Release Note

Model Name:	LP-201	object	<input type="radio"/> H.W. <input checked="" type="radio"/> S.W.
Subject:	Release Boot code of LP-201: lp201_boot.106		
Release content			
Bug fixed			
<p>1. modified boot program</p> <p>The original hardware is CPU GPIO Port A pin9 (N10), it is now changed to CPU GPIO Port C pin 17 (fxo loop). Therefore, the program is re-modified to automatic detection, which can be used on the new (H/W Ver 2.0A) also compatible with old hardware (H/W ver 2.0).</p>			
Feature and Function added			
Configuration item changed			
Note			