



Model Name:	Lp305	Object:	 H.W.  S.W.
Subject:	Release SIP firmware of LP305: LP305sip.101		
Release content			
Bug Fixed			
<ol style="list-style-type: none"> 1. Fixed under speaker mode the duplex voice problem. 2. Fixed when using above two accounts to register to the same Asterisk, it can't register successfully. 3. Fixed after picking up LP305 with speaker mode, the voice volume is always too low at first. 4. Improve voice quality. 5. Fixed press Keypad it can't be detected easily. 			
Feature and Function added			
<ol style="list-style-type: none"> 1. Support "canreinvite" function of Asterisk. 2. Support after receiving 183 message, it can send DTMF. 3. Added Quick setting function on LCD menu. LCD menu → 4. Phone Setting → 1. Quick Setup Wizard. 4. Password display method: It will be display " *** " instead of number or character. 5. Added User-defined time configuration without getting time from SNTP. LCD menu → 4. Phone Setting → 7. Time setting. (User can set the local time manual, don't need disable the SNTP feature, but the time by manual will be lose after system reboot) 			
Configuration item changed			
<ol style="list-style-type: none"> 1. Delete G723 CNG & VAD setting on WEB management. If user want to use CNG & VAD function in G711u, g711a, g723 and g729. User can set it from Telnet command line. For example: Voice -cng g729 1/0 (1/0: Enable/ Disable) 2. Rename "Flash Clean" to "Reset to Factory Value" on LCD management. 			
Note			
<ol style="list-style-type: none"> 1. Incomplete Feature <ol style="list-style-type: none"> 1.1 VLAN function. 1.2 Pbook's "insert" and "drop prefix" function. 1.3 Session timer. 1.4 DDNS function. 1.5 Prefix function. 			